

Source : RAN WG3 Chairman

Object: R99 Cover Sheet:

Release 1999 Submission form

Work Area / Item:		Support of soft handover during active compressed mode pattern			
Affects:	UE/MS:	CN:	UTRAN: X	Compatibility Issues:	Yes: No:
Expected Completion Date:		3/2000			
Services impacted:		Services using DCH			
Specifications affected:		25.433, 25.423			
Tasks within work which are not complete:			- Need to include compressed mode information also in Radio Link Setup and Radio Link Addition procedures.		
Consequences if not included in Release 1999:			It is impossible to add a radio link while a compressed mode pattern is active. CM must be deactivated before the RL addition, and then reactivated.		
Accepted by TSG#		for late inclusion in Release 1999:			