Report on test step RRC problems - v105

produced on: 21/11/2001 11:03:44

page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
010002	or_RB_SetupMO	v1.0.5	Line 8 + 10: TBDs should be resolved	Accepted - v106	14/11/2001
010004	or_RB_SetupMO	v1.0.5	No input in Comments fields in Test Body	Accepted - V110 - To clarify test cases, the step has been renamed to pr_GotoState6_5_Or6_7_MO	14/11/2001
010004	or_RB_SetupMO	v1.0.5	Test Step header input is missing in the Objective, Comments and Description field	Accepted - V110	14/11/2001
010004	or_RB_SetupMO	v1.0.5	Line 10-11: No Generic call set-up procedure for mobile originating circuit switched (cs) calls	Accepted - V106	14/11/2001

This report contains:

Number of problems: 4

Completed problems: 4