DL Scheduling DCI with
skipping/SS switching trigger
PDSCH
ACK
Processing time =
max(UE, gNB ACK)
K0
K1
Apply skipping for the
preconfigured slot
Resume DCI monitor
Or apply new SS

DL Scheduling DCI with
skipping/SS switching trigger
PDSCH
NACK
Retransmission DCI with
skipping/SS switching trigger
PDSCH
ACK
Processing time =
max(UE, gNB ACK)
K0
K1
K0
K1
Apply skipping for the
preconfigured slot
Resume DCI monitor
Or apply new SS