UE
Network
DCI to trigger beam report
Beam report by PUSCH
Failed to decode PUSCH and NW cannot identify new beam to recovery from uplink beam failure

UE
Network
MAC CE/DCI based beam indication
ACK by PUCCH
Failed to decode PUCCH and NW cannot update the TCI