SSB meas.
Set B is SSB?
no
(P2) CSI-RS meas.
yes
Predict Top-K TX-beams
K>1?
yes
(P2*) Top-K meas.
(CSI-RS)
no
Required when
no beam quality
is predicted if K=1
Optional P3 procedure
Data transmission