UE
Source eNodeB
Target eNodeB
MME
Source Serving GW
Target Serving GW
PDN GW
Downlink and uplink data
Handover preparation
Handover execution
Forwarding of data
0. RAN Data Reporting
Handover completion
Downlink data
Uplink data
1. Path Switch Request
2. Create Session Request
3a. Modify Bearer Request
3b. Modify Bearer Response
(A)
4. Create Session Response
Downlink data
5. Path Switch Request Ack
Uplink data
6. Release Resource
7a. Delete Session Request
(B)
7b. Delete Session Response
7c.Change Notification Request/Response
8. Tracking Area Update procedure