Report on test step RRC_M problems - v140

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
020036					
	ts_CMAC_NewU_RNTI_Reconf	**v1.4.0**	The Physical channels is not correctly set	Accepted - v150	16/09/2002
	ts_SHO_ReleaseDL_DPCH	**v1.4.0**	the temporary variable tcv_TmpCellinfo shall be assigned at the beginning of the step.	Accepted - v150	16/09/2002
	ts_SS_SetConfigRRC_RB3	**v1.4.0**	Configurations with DTCH shall be treated as well (for test cases tc_8_1_1_7, tc_8_1_1_8)	Accepted - v151	17/10/2002

This report contains:

Number of problems: 3

Completed problems: 3