CSI compression and decompression
Measured precoder before CSI compression
CSI after decompression
Apply the decompressed precoders to CSI-RS resources with port selection
CRI/CQI measurement
CRI = {0, 1, 4}, CQI = 10
CSI-RS