Source: **SA5 (Telecom Management)**

Title: **Rel-5 CR 32.111-3 (Fault Management; Part 3: Alarm Integration Reference Point: CORBA solution set version 1:1)**

Document for: **Approval**

Agenda Item: **7.5.3**

Doc-1st-	Spec	CR	Rev	Phase	Subject	Cat	Version-	Doc-2nd-	Workitem
SP-020476	32.111-3	017	-	Rel-5	**Addition of "indeterminate" probable cause in IDL definition**	F	5.0.0	S5-026467	OAM-NIM

CR-Form-v5

CHANGE REQUEST

| | ⌘ | **32.111-3** CR **017** | ⌘**rev** | **-** | ⌘ | Current version: | **5.0.0** | ⌘ |

*For **HELP** on using this form, see bottom of this page or look at the pop-up text over the ⌘ symbols.*

Proposed change affects: ⌘   (U)SIM ☐   ME/UE ☐   Radio Access Network **X**   Core Network **X**

Title:	⌘	Addition of "indeterminate" probable cause in IDL definition
Source:	⌘	SA5
Work item code: ⌘	OAM-NIM	*Date:* ⌘ 28/06/2002

Category:	⌘ **F**		*Release:* ⌘ REL-5

Use <u>one</u> of the following categories:
F (correction)
A (corresponds to a correction in an earlier release)
B (addition of feature),
C (functional modification of feature)
D (editorial modification)
Detailed explanations of the above categories can be found in 3GPP TR 21.900.

Use <u>one</u> of the following releases:
2 (GSM Phase 2)
R96 (Release 1996)
R97 (Release 1997)
R98 (Release 1998)
R99 (Release 1999)
REL-4 (Release 4)
REL-5 (Release 5)

Reason for change:	⌘	The "indeterminate" probable cause is missing.
Summary of change:	⌘	Addition of missing probable cause INDETERMINATE in interface "ProbableCause", in module "AlarmIRPConstDefs".
Consequences if not approved:	⌘	CORBA Solution Set (32.111-3) would be inconsistent with Information Service (32.111-2). See also "Other comments" below.

Clauses affected:	⌘	Annex A

Other specs affected:	⌘	☐ Other core specifications ⌘	
		☐ Test specifications	
		☐ O&M Specifications	

Other comments:	⌘	The "indeterminate" probable cause is present in:

- R99 Alarm IRP IS 32.111-2 V3.3.0 (2001-12)
- R4 Alarm IRP IS 32.111-2 V4.3.0 (2002-03)
- R5 Alarm IRP IS 32.111-2 V5.0.0 (2002-03)
- R99 Alarm IRP CORBA SS 32.111-3 V3.6.0 (2001-12)

Through R4 CR S5-026239 it has been added to R4 Alarm IRP CORBA SS.
It also needs to be added to R5 Alarm IRP CORBA SS.

Annex A (normative):
IDL specification (file name "AlarmIRPConstDefs.idl")

```
#ifndef AlarmIRPConstDefs_idl
•••
module AlarmIRPConstDefs
{
•••
   interface ProbableCause
   {
      const short INDETERMINATE = 0;
      const short ALARM_INDICATION_SIGNAL = 1;
•••
   };
•••
};
•••
```