UE
E-UTRAN
NG RAN
AMF
MME
SGW
PGW-C+ SMF
PGW-U+ UPF
1a. Handover command
1b. Handover command
DL Data forwarding
2a. Handover Complete
2b. Handover Notify
UL data (prepared bearers)
3. Modify bearer Request
4a. Modify bearer Request
4b. Sx Session Modification
5. Modify bearer Response
DL data (prepared bearers)
6. Modify bearer Response
7. PGW Initiated dedicated bearer activation
8. Tracking Area Update