TSG-RAN Meeting #13
Beijing, China, 18th – 21st September, 2001

Agenda Item: 9.2.6

Source: Rapporteur

Title: Status Report of Work Item Re-arrangement of lub Transport

Bearers

Document for: Information

Status

TR25.880 Re-arrangement of Iub Transport Bearers v. 0.1.0, rapporteurs update was presented during the RAN WG3#23 meeting and noted.

Open Issues

Following open issues are identified so far:

- Should the CRNC be able to trigger Iub Transport Bearers re-arrangement?
- Signalling bearer change timing: from when is the new signalling bearer used?
- Synchronised or unsynchronised configuration for bearer changes?

Proposal

There is no proposed actions for TSG RAN.