

Source : RAN WG3 Chairman

Object: R99 Cover Sheet:

**Release 1999 Submission form**

<b>Work Area / Item:</b>		<b>Support of soft handover during active compressed mode pattern</b>			
<b>Affects:</b>	<b>UE/MS:</b>	<b>CN:</b>	<b>UTRAN: X</b>	<b>Compatibility Issues:</b>	<b>Yes: No:</b>
<b>Expected Completion Date:</b>		3/2000			
<b>Services impacted:</b>		Services using DCH			
<b>Specifications affected:</b>		25.433, 25.423			
<b>Tasks within work which are not complete:</b>			- Need to include compressed mode information also in Radio Link Setup and Radio Link Addition procedures.		
<b>Consequences if not included in Release 1999:</b>			It is impossible to add a radio link while a compressed mode pattern is active. CM must be deactivated before the RL addition, and then reactivated. Means increased dropped call rate.		
<b>Accepted by TSG#</b>		<b>for late inclusion in Release 1999:</b>			