

Report on test step RRC problems - v110

produced on: 05/04/2002 09:25:43

page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
020017					
	ts_CreateCell_GPRS_Comb	v1.1.0	Variables tcv_G_CellInfoConfig and tcv_G_GPRS_ConfigInfo are located as Test Suite Variables. This means that either the prefix or the location is incorrect.	Accepted - v120 - done - Object name: tcv_G_GPRS_ConfigInfo	22/01/2002
	ts_CreateCell_GPRS_Comb	v1.1.0	tcv_G_GPRS_ConfigInfo not initialized	Accepted - v121 - The constraint c_G_GPRS_ConfigInfoDef has been created.	25/03/2002
	ts_SendSysInfoType1	v1.1.0	Variables tcv_G_CellInfoConfig and tcv_G_GPRS_ConfigInfo are located as Test Suite Variables. This means that either the prefix or the location is incorrect.	Accepted - v120 - done - Object name: tcv_G_CellInfoConfig	22/01/2002
	ts_SendSysInfoType1	v1.1.0	tcv_G_CellConfigInfo not initialized	Accepted - v121 - done	01/03/2002

This report contains:

Number of problems: 4

Completed problems: 4