

Report on test step SMS problems - v110

produced on: 14/02/2002 11:06:37
page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
020011					

ts_AT_CNMI

v1.1.0

ME is configured to provide new message indications by using the AT command '+CNMI=0,2'. Syntax for 'CNMI' command is (Reference clause 3.4.1 of 27.005)+CNMI=[<mode>[,<mt>[,<bm>[,<ds>[,<bfr>]]]] - <mt>=2 implies to route SMS-DELIVER to TE using unsolicited result code. But with <mode>=0, all the unsolicited result codes will be buffered in TA. Nothing will be sent to TE. <mode>=3 configure ME to forward unsolicited result codes directly to the TE. Hence we think that AT command '+CNMI=3,2' is needed to set the ME to provide new message indications.

Accepted - v120 - Done

10/01/2002

This report contains:

Number of problems: 1

Completed problems: 1