

Report on test step RLC problems - v120

produced on: 05/04/2002 09:27:18

page 1 of 1

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
---------------------	----------------	---------	---------	---------------------------	-----------

020016

po_GenericCleanupProcedures

v1.2.0

" In it there is an RB release at line 2. Is there a reason why this is done? When doing RRC conn release at the end, all RBs will be released anyway. According to 34.109 5.2.2.2 it says that you just need an RRC connection to do the deactivation of the test mode (and of course that the mode is active). So, if you do a deactivation of the test mode, without doing any RB release first, and right after that you do an RRC connection release (inside po_ConnectionAndSS_Rel) would you not achieve the same?"

Accepted - v121 - The RB release is not needed. 07/02/2002

This report contains:

Number of problems: 1

Completed problems: 1