

Report on test step L3M problems - v140

produced on: 14/11/2002 11:07:57
page 1 of 2

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
020033					
	ts_CC_TelephonyMO	v1.4.0	"RepeatInd" is declared as a simple type, where the type definition is ""B8". This needs to change to a structured type with two fields. This is to achieve consistency with other single-octet Tag/Value IEs.	Accepted - v150	08/08/2002
020035					
	ts_CC_BS30MO	v1.4.0	tsc_BcapMT_Any has the value '?????'B - A test suite constant cannot be assigned wildcards. Replace tsc_BcapMT_Any in the constraint with the value '?????'B.	Accepted - v150	05/09/2002
020036					
	ts_CC_BS20MO	v1.4.0	Two specific constraints shall be defined (cr_FacilityAdvRecall and cr_FacilityRecallAlign) to receive Facility IEs for Adv recall and recall Align services.	Accepted - v150	16/09/2002
	ts_CC_TS61_MO	v1.4.0	Two specific constraints shall be defined (cr_FacilityAdvRecall and cr_FacilityRecallAlign) to receive Facility IEs for Adv recall and recall Align services.	Accepted - v150	16/09/2002
020037					
	ts_CC_BS20MO	v1.4.0	Assignment of wild cards to TSVs and TCVs is not legal.	Accepted - v151?	?
020038					
	ts_CC_BS20MO	v1.4.0	Assignment of wild cards to TSVs and TCVs is not legal.	Accepted - v151	03/10/2002

Report on test step L3M problems - v140

produced on: 14/11/2002 11:07:57
page 2 of 2

Nr. of error report	Test step name	Version	Problem	Comment from MCC Task 160	Done date
---------------------	----------------	---------	---------	---------------------------	-----------

This report contains:

Number of problems: 6

Completed problems: 5