

Source : RAN WG3 Chairman

Object: R99 Cover Sheet:

Release 1999 Submission form

Work Area / Item:		Physical channel reconfiguration procedure on Iur			
Affects:	UE/MS:	CN:	UTRAN: X	Compatibility Issues:	Yes: No:
Expected Completion Date:		3/2000			
Services impacted:		Not service related			
Specifications affected:		25.423			
Tasks within work which are not complete:			- Crossing signalling and interaction with other procedures (this procedure is initiated from the "wrong" direction)		
Consequences if not included in Release 1999:			No possibility for CRNC to reshuffle the code-tree (i.e. worse radio performance)		
Accepted by TSG#		for late inclusion in Release 1999:			