NOTE 1: Test cases in green are ready for verification.
NOTE 2: Test cases that are supplied for visual inspection and comment only.

A.2 NAS ATS

The approved NAS test cases are listed.

Table A.2: NAS TTCN test cases

Test case	Description
	MM
tc_9_1	TMS1 reallocation
tc_9_2_1	Authentication accepted
tc_9_2_2	Authentication rejected by the network
tc_9_2_3	Authentication rejected by the UE (MAC code failure)
tc_9_2_4	Authentication rejected by the UE (SQN failure)
tc_9_3_1	General Identification
tc_9_3_2	Handling of IMSI shorter than the maximum length.
tc_9_4_1	Location updating / accepted
tc_9_4_2_1	Location updating / rejected / IMSI invalid
tc_9_4_2_2_1	Location updating / rejected / PLMN not allowed – test 1
tc_9_4_2_2_2	Location updating / rejected / PLMN not allowed – test 2
tc_9_4_2_3	Location updating / rejected / location area not allowed
tc_9_4_2_4_1	Location updating rejected / roaming not allowed in this location area – procedure 1
tc_9_4_2_4_2	Location updating rejected / roaming not allowed in this location area – procedure 2
tc_9_4_2_4_3	Location updating rejected / roaming not allowed in this location area – procedure 3
tc_9_4_2_4_4	Location updating rejected / roaming not allowed in this location area – procedure 4
tc_9_4_2_4_5	Location updating rejected / roaming not allowed in this location area – procedure 5
tc_9_4_2_5	Location Updating / Rejected / No Suitable Cells In Location Area
tc_9_4_3_2	Location Updating / Abnormal cases / Attempt counter less or equal to 4, LAI different
tc_9_4_3_3	Location Updating / Abnormal cases/ Attempt Counter Equal to 4
tc_9_4_3_4	Location Updating / Abnormal cases / Attempt Counter less or equal to 4, stored LAI equal to broadcast LAI
tc_9_4_4	Location updating / release / expiry of T3240
tc_9_4_5_1	Location updating / periodic spread
tc_9_4_5_2	Location updating / periodic normal / test 1
tc_9_4_5_3	Location updating / periodic normal / test 2
tc_9_4_5_4_1	Location Updating / Periodic HPLMN search / UE waits time T.
tc_9_4_5_4_2	Location Updating / Periodic HPLMN search / UE in manual mode
tc_9_4_5_4_3	Location Updating / Periodic HPLMN search / UE waits at least two minutes and at most T minutes
tc_9_4_6	Location updating / interworking of attach and periodic
tc_9_5_2	MM connection / establishment with cipher
tc_9_5_3	MM connection / establishment without cipher
tc_9_5_4	MM connection / establishment rejected
tc_9_5_5	MM connection / establishment rejected cause 4
tc_9_5_6	MM connection / expiry T3230
tc_9_5_7_1	MM connection / abortion by the network / cause #6
tc_9_5_7_2	MM connection / abortion by the network / cause not equal to #6
tc_9_5_8_1	MM connection / follow-on request pending / test 1
tc_9_5_8_2	MM connection / follow-on request pending / test 2
tc_9_5_8_3	MM connection / follow-on request pending / test 3 CC
tc_10_1_2_1_1	Outgoing call / U0 null state / MM connection requested
tc_10_1_2_1_1	Outgoing call / U0.1 MM connection pending / CM service rejected
tc_10_1_2_2_1	Outgoing call / U0.1 MM connection pending / CM service accepted
tc_10_1_2_2_3	Outgoing call / U0.1 MM connection pending / lower layer failure
tc_10_1_2_3_1	Outgoing call / U1 call initiated / receiving CALL PROCEEDING
tc_10_1_2_3_2	Outgoing call / U1 call initiated / rejecting with RELEASE COMPLETE
tc_10_1_2_3_3	Outgoing call / U1 call initiated / T303 expiry
tc_10_1_2_3_4	Outgoing call / U1 call initiated / lower layer failure
v_	

Test case	Description
	Outgoing call / U1 call initiated / receiving ALERTING
	Outgoing call / U1 call initiated / entering state U10
	Outgoing call / U1 call initiated / unknown message received
	Outgoing call / U3 UE originating call proceeding / ALERTING received
	Outgoing call / U3 UE originating call proceeding / CONNECT received
tc_10_1_2_4_3	Outgoing call / U3 UE originating call proceeding / PROGRESS received without in band information
	Outgoing call / U3 UE originating call proceeding / / PROGRESS with in band information
	Outgoing call / U3 UE originating call proceeding / DISCONNECT with in band tones
	Outgoing call / U3 UE originating call proceeding / DISCONNECT without in band tones Outgoing call / U3 UE originating call proceeding / RELEASE received
	Outgoing call / U3 UE originating call proceeding / RELEASE received Outgoing call / U3 UE originating call proceeding / termination requested by the user
	Outgoing call / U3 UE originating call proceeding / traffic channel allocation
	Outgoing call / U3 UE originating call proceeding / timer T310 time-out
	Outgoing call / U3 UE originating call proceeding / lime 1916 time out
	Outgoing call / U3 UE originating call proceeding / unknown message received
	Outgoing call / U3 UE originating call proceeding / CONNECT received
	Outgoing call / U4 call delivered / CONNECT received
	Outgoing call / U4 call delivered / termination requested by the user
	Outgoing call / U4 call delivered / DISCONNECT with in band tones
tc_10_1_2_5_4	Outgoing call / U4 call delivered / DISCONNECT without in band tones
tc_10_1_2_5_5	Outgoing call / U4 call delivered / RELEASE received
tc_10_1_2_5_6	Outgoing call / U4 call delivered / lower layer failure
	Outgoing call / U4 call delivered / traffic channel allocation
	Outgoing call / U4 call delivered / unknown message received
	U10 call active / termination requested by the user
	U10 call active / RELEASE received
	U10 call active / DISCONNECT with in band tones
	U10 call active / DISCONNECT without in band tones
	U10 call active / RELEASE COMPLETE received
	U10 call active / SETUP received U11 disconnect request / clear collision
	U11 disconnect request / RELEASE received
	U11 disconnect request / timer T305 time-out
	U11 disconnect request / lower layer failure
	U11 disconnect request / unknown message received
tc_10_1_2_8_1	U12 disconnect indication / call releasing requested by the user
	U12 disconnect indication / RELEASE received
	U12 disconnect indication / lower layer failure
	U12 disconnect indication / unknown message received
tc_10_1_2_9_1	Outgoing call / U19 release request / timer T308 time-out
	Outgoing call / U19 release request / 2 nd timer T308 time-out
tc_10_1_2_9_3 tc_10_1_2_9_4	Outgoing call / U19 release request / RELEASE received Outgoing call / U19 release request / RELEASE COMPLETE received
	Outgoing call / U19 release request / RELEASE COMPLETE received Outgoing call / U19 release request / lower layer failure
	Incoming call / U0 null state / SETUP received with a non supported bearer capability
	Incoming call / U6 call present / automatic call rejection
	Incoming call / U9 mobile terminating call confirmed / alerting or immediate connecting
	Incoming call / U9 mobile terminating call confirmed / DTCH assignment
tc_10_1_3_3_3	Incoming call / U9 mobile terminating call confirmed / termination requested by the user
	Incoming call / U9 mobile terminating call confirmed / DISCONNECT received
	Incoming call / U9 mobile terminating call confirmed / RELEASE received
	Incoming call / U9 mobile terminating call confirmed / lower layer failure
	Incoming call / U9 mobile terminating call confirmed / unknown message received
	Incoming call / U7 call received / call accepted
	Incoming call / U7 call received / termination requested by the user
	Incoming call / U7 call received / DISCONNECT received
	Incoming call / U7 call received / RELEASE received
	Incoming call / U7 call received / lower layer failure
	Incoming call / U7 call received / DTCH assignment Incoming call / U7 call received / unknown message received
	Incoming call / U7 call received / BELEASE COMPLETE received
	Incoming call / U8 connect request / CONNECT acknowledged
.0_10_1_0_0_1	and the state of t

Test case	Description
	Description
	Incoming call / U8 connect request / timer T313 time-out
	Incoming call / U8 connect request / termination requested by the user
	Incoming call / U8 connect request / DISCONNECT received with in-band information
	Incoming call / U8 connect request / DISCONNECT received without in-band information
	Incoming call / U8 connect request / RELEASE received
	Incoming call / U8 connect request / lower layer failure
	Incoming call / U8 connect request / DTCH assignment
	Incoming call / U8 connect request / unknown message received
	In-call functions / DTMF information transfer / basic procedures
	In-call functions / User notification / UE terminated
	In-call functions / channel changes / a successful channel change in active state / Hard handover
	In-call function / channel changes / an unsuccessful channel change in active mode / Hard Handover
tc_10_2_1	Call Re-establishment/call present, re-establishment allowed
tc_10_3	User to user signalling
	Session Management
	Attach initiated by context activation/QoS Offered by Network is the QoS Requested
tc_11_1_1_2_1	QoS accepted by UE
tc_11_1_1_2_2	QoS rejected by UE
tc_11_1_2	PDP context activation requested by the network, successful and unsuccessful
tc_11_1_3_1	T3380 Expiry
tc_11_1_3_2	Collision of UE initiated and network requested PDP context activation
tc_11_1_3_3	Network initiated PDP context activation request for an already activated PDP context (on the UE side)
tc_11_1_4_1_1	QoS Offered by Network is the QoS Requested
	QoS accepted by UE
	QoS rejected by UE
	Unsuccessful Secondary PDP Context Activation Procedure Initiated by the UE
	T3380 Expiry
tc_11_2_1	Collision of UE and network initiated PDP context modification procedures
	PDP context deactivation initiated by the UE
	T3390 Expiry
	PDP context deactivation initiated by the network
tc_11_2_3_2	Collision of UE and network initiated PDP context deactivation requests
tc_11_3_1	Network initiated PDP context modification
tc_11_3_2	UE initiated PDP Context Modification accepted by network
tc_11_3_3_1	UE initiated PDP Context Modification not accepted by the network
	T3381 Expiry
tc_11_4_1	Error cases
	GPRS Mobility Management
tc_12_2_1_1	PS attach / accepted
tc_12_2_1_2	PS attach / rejected / IMSI invalid / illegal UE
	PS attach / rejected / IMSI invalid / PS services not allowed
	PS attach / rejected / IMSI invalid / PLMN not allowed / procedure 1
	PS attach / rejected / IMSI invalid / PLMN not allowed / procedure 2
	PS attach / rejected / roaming not allowed in this location area / test procedure 1
	PS attach / rejected / roaming not allowed in this location area / test procedure 2
	PS attach / rejected / roaming not allowed in this location area / test procedure 3
	PS attach / rejected / roaming not allowed in this location area / test procedure 4
	PS attach / rejected / No Suitable Cells In Location Area
	PS attach /abnormal cases / access barred due to access class control / procedure 1
	PS attach /abnormal cases / access barred due to access class control / procedure 2
	PS attach / abnormal cases / change of cell into new routing area
	PS attach / abnormal cases / power off
tc_12_2_1_9	PS attach / abnormal cases / PS detach procedure collision
tc_12_2_2_1	Combined PS attach / PS and non-PS attach accepted
tc_12_2_2_1	Combined PS attach / PS only attach accepted / procedure 1
	Combined PS attach / PS only attach accepted / procedure 2
tc_12_2_3	Combined PS attach / PS attach while IMSI attach
tc_12_2_2_4	Combined PS attach / rejected / IMSI invalid / illegal ME
tc_12_2_5	Combined PS attach / rejected / PS services and non-PS services not allowed
tc_12_2_2_6	Combined PS attach / rejected / PS services not allowed
tc_12_2_2_7a	Combined PS attach / rejected / location area not allowed
tc_12_2_2_7b	Combined PS attach / rejected / No Suitable Cells In Location Area
· ·	- I I I I I I I I I I I I I I I I I I I

Test case	Description
tc_12_2_2_8	Combined PS attach / abnormal cases / attempt counter check / miscellaneous reject causes
tc_12_2_2_9	Combined PS attach / abnormal cases / PS detach procedure collision
	PS detach (NMO II) / power off / accepted
	PS detach / accepted
	PS detach / abnormal cases / attempt counter check / procedure timeout
tc_12_3_1_4	PS detach / abnormal cases / GMM common procedure collision
	PS detach (NMO I) / power off / accepted
	PS detach (NMO I) / accepted / PS/IMSI detach
	PS detach / accepted / IMSI detach
	PS detach / abnormal cas es / change of cell into new routing area
	PS detach (NMO I) / abnormal cases / PS detach procedure collision
tc_12_3_2_1	Network initiated PS detach/ re-attach not required / accepted
	PS detach / rejected / IMSI invalid / PS services not allowed
	Network initiated PS detach / IMSI detach / accepted
	Network initiated PS detach/ re-attach requested / accepted
	Network initiated PS detach / rejected / location area not allowed
	PS detach / rejected / No Suitable Cells In Location Area
	Routing area updating / accepted Routing area updating / rejected /IMSI invalid / illegal ME
	Routing area updating / rejected /IMSI invalid / illegal ME Routing area updating / rejected / UE identity cannot be derived by the network
	Routing area updating / rejected / OE identity carnot be derived by the network Routing area updating / rejected / location area not allowed
	Routing area updating / rejected / No Suitable Cells In Location Area
	Routing area updating / abnormal cases /attempt counter check / miscellaneous reject causes
	Routing area updating / abnormal cases / change of cell into new routing area
	Routing area updating / abnormal cases / change of cell during routing area procedure
	Routing area updating / abnormal cases / P-TMSI reallocation procedure collision
tc_12_4_2_1	Combined routing area updating / combined RA/LA accepted
tc_12_4_2_2	Combined routing area updating / UE in CS operation at change of RA
tc_12_4_2_3_1	Combined routing area updating / RA only accepted / procedure 1
	Combined routing area updating / RA only accepted / procedure 2
	Combined routing area updating / rejected / PLMN not allowed
	Combined routing area updating / rejected / roaming not allowed in this location area / procedure 1
tc_12_4_2_5a_2 tc_12_4_2_5b	Combined routing area updating / rejected / roaming not allowed in this location area / procedure 2 Combined routing area updating / rejected / No Suitable Cells In Location Area
	Combined routing area updating / rejected / No Suitable Cells III Education Area Combined routing area updating / abnormal cases /access barred due to access class control /
	procedure 1
	Combined routing area updating / abnormal cases /access barred due to access class control / procedure 2
tc_12_4_2_7	Combined routing area updating / abnormal cases / attempt counter check / procedure timeout
tc_12_4_2_8	Combined routing area updating / abnormal cases / change of cell into new routing area
	Combined routing area updating / abnormal cases / change of cell during routing area procedure
	Combined routing area updating / abnormal cases / PS detach procedure collision / procedure 1
	Combined routing area updating / abnormal cases / PS detach procedure collision / procedure 2
	Periodic routing area updating / accepted
	Periodic routing area updating / accepted / T3312 default value
	Periodic routing area updating / no cell available / network mode I
tc_12_4_3_4	Periodic routing area updating and periodic location area updating / no cell available
	P-TMSI reallocation PS authentication and ciphering / Authentication accepted
	PS authentication and ciphering / Authentication accepted PS authentication and ciphering / Authentication rejected by the network
	Authentication rejected by the UE / GMM cause 'MAC failure'
	Authentication rejected by the UE / GMM cause 'Synch failure'
	Authentication rejected by the UE / fraudulent network
tc_12_7	Identification procedure
tc_12_8	GMM READY timer handling
tc_12_9_1	Service Request initiated by the UE
tc_12_9_2	Service Request initiated by the network
tc_12_9_3	Service Request / rejected / Illegal MS
tc_12_9_4	Service Request / rejected / PS services not allowed
tc_12_9_5	Service Request / rejected / MS identity cannot be derived by the network
	Service Request / rejected / PLMN not allowed
tc_12_9_7a	Service Request / rejected / No PDP context activated

Test case	Description
tc_12_9_7b	Service Request / rejected / No Suitable Cells In Location Area
tc_12_9_8	Service Request / Abnormal cases/ Access barred due to access control
tc_12_9_9	Service Request / Abnormal cases/ Collision with Routing Area Update procedure
tc_12_9_10	Service Request / Abnormal cases / Power off
tc_12_9_11	Service Request / Abnormal cases / Service Request procedure collision
	General Tests
tc_13_2_1_1	Emergency call / with USIM / accept case
tc_13_2_2_1	Emergency call / without USIM / accept case
tc_13_2_2_2	Emergency call / without USIM / reject case
	User Equipment features
tc_17_1_2	Test of autocalling restrictions/ Constraining the access to a single number (TS 22.001 category 3)
tc_17_1_3	Test of autocalling restrictions/ Constraining the access to a single number (TS 22.001 category 1 and 2)
tc_17_1_4	Test of autocalling restrictions/ Behaviour of the UE when its list of blacklisted numbers is full

A.3 SMS ATS

The approved SMS test cases are listed.

Table A.3: SMS TTCN test cases

Test case	Description
tc_16_1_1	SMS point to point on CS mode / SMS mobile terminated
tc_16_1_2	SMS point to point on CS mode / SMS mobile originated
tc_16_1_3	SMS point to point on CS mode / Test of memory full condition and memory available notification:
tc_16_1_4	SMS point to point on CS mode / Test of the status report capabilities and of SMS-COMMAND:
tc_16_1_5_1	SMS point to point on CS mode / Short message class 0
tc_16_1_5_2	SMS point to point on CS mode / Test of class 1 short messages
tc_16_1_5_3	SMS point to point on CS mode / Test of class 2 short messages
tc_16_1_7	SMS point to point on CS mode / Test of the replace mechanism for SM type 1-7
tc_16_1_8	SMS point to point on CS mode / Test of the reply path scheme
tc_16_1_9_1	SMS point to point on CS mode / UE in idle mode
tc_16_1_9_2	SMS point to point on CS mode / UE in active mode
tc_16_1_10	SMS point to point on CS mode / Test of capabilities of simultaneously receiving a short message
	whilst sending a mobile originated short message
tc_16_2_1	Short message service point to point on PS mode / SMS mobile terminated
tc_16_2_2	Short message service point to point on PS mode / SMS mobile originated
tc_16_2_3	Short message service point to point on PS mode / Test of memory full condition and memory
	available notification:
tc_16_2_4	Short message service point to point on PS mode / Test of the status report capabilities and of SMS-COMMAND:
tc_16_2_5_1	Short message service point to point on PS mode / Short message class 0
tc_16_2_5_2	Short message service point to point on PS mode / Test of class 1 short messages
tc_16_2_5_3	Short message service point to point on PS mode / Test of class 2 short messages
tc_16_2_7	Short message service point to point on PS mode / Test of the replace mechanism for SM type 1-7
tc_16_2_8	Short message service point to point on PS mode / Test of the reply path scheme
tc_16_2_10	Short message service point to point on PS mode / Test of capabilities of simultaneously receiving a
	short message whilst sending a mobile originated short message
tc_16_3	Short message service cell broadcast

A.4 RRC ATS

The approved RRC test cases are listed.

Table A.4: RRC TTCN test cases

Test case	Description
10 0 1 1	Singlecell
tc_8_1_1_1 tc_8_1_1_2	Paging for Connection in idle mode Paging for Connection in connected mode (CELL_PCH)
tc_8_1_1_3	Paging for Connection in connected mode (CELL_PCH) Paging for Connection in connected mode (URA_PCH)
tc_8_1_1_4	Paging for Notification in idle mode
tc_8_1_1_5	Paging for Notification in connected mode (CELL_PCH)
tc_8_1_1_6	Paging for Notification in connected mode (URA_PCH)
tc_8_1_1_7	Paging for Connection in connected mode (CELL_DCH)
tc_8_1_1_8	Paging for Connection in connected mode (CELL_FACH)
tc_8_1_2_1	RRC Connection Establishment in CELL_DCH state: Success
tc_8_1_2_2	RRC Connection Establishment: Success after T300 timeout
tc_8_1_2_3	RRC Connection Establishment: Failure (V300 is greater than N300)
tc_8_1_2_4	RRC Connection Establishment: Reject ("wait time" is not equal to 0)
tc_8_1_2_5	RRC Connection Establishment: Reject ("wait time" is not equal to 0 and V300 is greater than N300)
tc_8_1_2_6	RRC Connection Establishment: Reject ("wait time" is set to 0)
tc_8_1_2_7	RRC Connection Establishment in CELL_FACH state: Success
tc_8_1_2_9	RRC Connection Establishment: Success after Physical channel failure and Invalid configuration
tc_8_1_3_1	RRC Connection Release in CELL_DCH state: Success
tc_8_1_3_2	RRC Connection Release using on DCCH in CELL_FACH state: Success
tc_8_1_3_3	RRC Connection Release using on CCCH in CELL_FACH state: Success
tc_8_1_3_4	RRC Connection Release in CELL_FACH state: Failure
tc_8_1_3_5	RRC Connection Release in CELL_FACH state: Invalid message
tc_8_1_5_1	UE Capability in CELL_DCH state: Success UE Capability in CELL_DCH state: Success after T304 timeout
tc_8_1_5_2	
tc_8_1_5_3 tc_8_1_5_4	UE Capability in CELL_DCH state: Failure (After N304 re-transmissions) UE Capability in CELL_FACH state: Success
tc_8_1_5_5	UE Capability in CELL_FACH state: Success after T304 timeout
tc_8_1_6_1	Direct Transfer in CELL DCH state (invalid message reception and no signalling connection exists)
tc_8_1_6_2	Direct Transfer in CELL FACH state (invalid message reception and no signalling connection exists)
tc_8_1_7_1	Security mode command in CELL_DCH state
tc_8_1_7_2	Security mode command in CELL_FACH state
tc_8_1_8_1	Counter check in CELL_DCH state
tc_8_1_8_2	Counter check in CELL_FACH state
tc_8_1_9	Signalling Connection Release Request
tc_8_2_1_1	Radio Bearer Establishment for transition from CELL_DCH to CELL_DCH: Success
tc_8_2_1_3	Radio Bearer Establishment for transition from CELL_DCH to CELL_DCH: Failure (Unsupported
	configuration)
tc_8_2_1_4	Radio Bearer Establishment for transition from CELL_DCH to CELL_DCH: Failure (Physical channel
	Failure and successful reversion to old configuration)
tc_8_2_1_5	Radio Bearer Establishment for transition from CELL_DCH to CELL_DCH: Failure (Physical channel
to 0 0 1 0	Failure and reversion failure)
tc_8_2_1_6	Radio Bearer Establishment for transition from CELL_DCH to CELL_DCH: Failure (Incompatible simultaneous reconfiguration)
tc_8_2_1_7	Radio Bearer Establishment for transition from CELL_DCH to CELL_DCH: Failure (Invalid message
10_0_2_1_1	reception and Invalid configuration)
tc_8_2_1_8	Radio Bearer Establishment for transition from CELL_DCH to CELL_FACH: Success
tc_8_2_1_9	Radio Bearer Establishment for transition from CELL_DCH to CELL_FACH: Success (Cell re-
	selection)
tc_8_2_1_10	Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Success
tc_8_2_1_11	Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Failure (Unsupported
	configuration)
tc_8_2_1_12	Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Failure (Physical channel
	Failure and successful reversion to old configuration)
tc_8_2_1_13	Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Failure (Physical channel
40 0 0 4 44	Failure and reversion failure)
tc_8_2_1_14	Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Failure (Incompatible
tc_8_2_1_15	simultaneous reconfiguration) Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Failure (Invalid message
10_0_2_1_13	reception and Invalid configuration)
tc_8_2_1_16	Radio Bearer Establishment for transition from CELL_FACH to CELL_FACH: Success
tc_8_2_1_10	Radio Bearer Establishment for transition from CELL_PACITIO CELL_PACITION CELL CELL CELL CELL CELL CELL CELL CEL
.0_0_2_1_11	Trade Dearer Location montrer transaction from OLLE_Don't to OLLE_Don't Success (Outsetherity)

Test case	Description
	received)
tc_8_2_1_18	Radio Bearer Establishment for transition from CELL_FACH to CELL_DCH: Success (Subsequently
**_*	received)
tc_8_2_1_19	Radio Bearer Establishment from CELL_DCH to CELL_PCH: Success
tc_8_2_1_20	Radio Bearer Establishment from CELL DCH to URA PCH: Success
tc_8_2_2_1	Radio Bearer Reconfiguration (Hard handover) from CELL_DCH to CELL_DCH: Success
tc_8_2_2_2	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Failure (Unsupported configuration)
tc_8_2_2_3	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Failure (Physical channel failure and
10_0_10	reversion to old configuration)
tc_8_2_2_4	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Failure (Physical channel failure and
**_*	reversion failure)
tc_8_2_2_5	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Failure (Incompatible simultaneous
	reconfiguration)
tc_8_2_2_6	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Failure (Invalid message reception
_	and Invalid configuration)
tc_8_2_2_7	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Success (Continue and stop)
tc_8_2_2_8	Radio Bearer Reconfiguration from CELL_DCH to CELL_FACH: Success
tc_8_2_2_9	Radio Bearer Reconfiguration from CELL_DCH to CELL_FACH: Success (Cell re-selection)
tc_8_2_2_10	Radio Bearer Reconfiguration: from CELL_FACH to CELL_DCH: Success
tc_8_2_2_11	Radio Bearer Reconfiguration from CELL_FACH to CELL_DCH: Failure (Unsupported configuration)
tc_8_2_2_12	Radio Bearer Reconfiguration from CELL_FACH to CELL_DCH: Failure (Physical channel failure and
	reversion to old configuration)
tc_8_2_2_13	Radio Bearer Reconfiguration from CELL_FACH to CELL_DCH: Failure (Physical channel failure and
	reversion failure)
tc_8_2_2_14	Radio Bearer Reconfigure from CELL_FACH to CELL_DCH: Failure (Incompatible simultaneous
	reconfiguration)
tc_8_2_2_15	Radio Bearer Reconfiguration from CELL_FACH to CELL_DCH: Failure (Invalid message reception
	and Invalid configuration)
tc_8_2_2_16	Radio Bearer Reconfiguration from CELL_FACH to CELL_ FACH: Success (Continue and Stop)
tc_8_2_2_17	Radio Bearer Reconfiguration from CELL_FACH to CELL_FACH: Success
tc_8_2_2_18	Radio Bearer Reconfiguration from CELL_FACH to CELL_FACH: Success (Cell re-selection)
tc_8_2_2_19	Radio Bearer Reconfiguration from CELL_DCH to CELL_DCH: Success (Subsequently received)
tc_8_2_2_20	Radio Bearer Reconfigure from CELL_FACH to CELL_DCH: Success (Subsequently received)
tc_8_2_2_21	Radio Bearer Reconfiguration from CELL_DCH to CELL_PCH: Success
tc_8_2_2_22	Radio Bearer Reconfiguration from CELL_DCH to URA_PCH: Success
tc_8_2_2_23	Radio Bearer Reconfiguration from CELL_FACH to CELL_PCH: Success
tc_8_2_2_24 tc_8_2_3_1	Radio Bearer Reconfiguration from CELL_FACH to URA_PCH: Success Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Success
tc_8_2_3_1	Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Success Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Failure (Unsupported)
10_0_2_3_2	configuration)
tc 8 2 3 3	Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Failure (Physical channel failure
10_0_2_5_5	and reversion to old configuration)
tc_8_2_3_4	Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Failure(Physical channel failure
10_0_2_0_1	and reversion failure)
tc_8_2_3_5	Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Failure (Incompatible
	simultaneous reconfiguration)
tc_8_2_3_6	Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Failure (Invalid message
	reception and Invalid configuration)
tc_8_2_3_7	Radio Bearer Release for transition from CELL_DCH to CELL_FACH: Success
tc_8_2_3_8	Radio Bearer Release for transition from CELL_DCH to CELL_FACH: Success (Cell re-selection)
tc_8_2_3_9	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Success
tc_8_2_3_10	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Failure (Unsupported
	configuration)
tc_8_2_3_11	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Failure (Physical channel
	failure and reversion to old configuration)
tc_8_2_3_12	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Failure (Physical channel
4- 0 0 0 10	failure and reversion failure)
tc_8_2_3_13	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Failure (Incompatible
4- 0-0-0-11	simultaneous reconfiguration)
tc_8_2_3_14	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Failure (Invalid message
to 9 2 2 45	reception and Invalid configuration) Radio Bearer Release for transition from CELL_FACH to CELL_FACH: Success
tc_8_2_3_15	Radio Bearer Release for transition from CELL_FACH to CELL_FACH: Success Radio Bearer Release for transition from CELL_DCH to CELL_DCH: Success (Subsequently
tc_8_2_3_16	Radio Deale: Release for transition from CELL_DCR to CELL_DCR. Success (Subsequently

Test case	Description
	received)
tc_8_2_3_17	Radio Bearer Release for transition from CELL_FACH to CELL_DCH: Success (Subsequently received)
tc_8_2_3_18	Radio Bearer Release from CELL_DCH to CELL_PCH: Success
tc_8_2_3_19	Radio Bearer Release from CELL_DCH to URA_PCH: Success
tc_8_2_4_1	Transport channel reconfiguration from CELL_DCH to CELL_DCH (Hard handover to same radio frequency): Success with no transport channel type switching
tc_8_2_4_1a	Transport channel reconfiguration (Transmission Rate Modification with Timing Maintained) from CELL_DCH to CELL_DCH of the same cell :Success.
tc_8_2_4_2	Transport channel reconfiguration from CELL_DCH to CELL_DCH: Failure (Unsupported configuration)
tc_8_2_4_3	Transport channel reconfiguration from CELL_DCH to CELL_DCH: Failure (Physical channel failure and reversion to old configuration)
tc_8_2_4_4	Transport channel reconfiguration from CELL_DCH to CELL_DCH: Failure (Physical channel failure and reversion failure)
tc_8_2_4_5	Transport Channel Reconfiguration from CELL_DCH to CELL_DCH: Failure (Incompatible simultaneous reconfiguration)
tc_8_2_4_6	Transport channel reconfiguration from CELL_DCH to CELL_DCH: Failure (Invalid message reception and Invalid configuration)
tc_8_2_4_7	Transport channel reconfiguration from CELL_DCH to CELL_FACH: Success
tc_8_2_4_9	Transport channel reconfiguration from CELL_DCH to CELL_FACH: Success (Cell re-selection)
tc_8_2_4_10	Transport channel reconfiguration from CELL_FACH to CELL_DCH: Success
tc_8_2_4_11	Transport channel reconfiguration from CELL_FACH to CELL_DCH: Failure (Unsupported configuration)
tc_8_2_4_12	Transport channel reconfiguration from CELL_FACH to CELL_DCH: Failure (Physical channel failure and reversion to old channel)
tc_8_2_4_13	Transport channel reconfiguration from CELL_FACH to CELL_DCH: Failure (Physical channel failure and reversion failure)
tc_8_2_4_14	Transport Channel Reconfiguration from CELL_FACH to CELL_DCH: Failure (Incompatible simultaneous reconfiguration)
tc_8_2_4_15	Transport channel reconfiguration from CELL_FACH to CELL_DCH: Failure (Invalid message reception and Invalid configuration)
tc_8_2_4_16	Transport channel reconfiguration from CELL_FACH to CELL_FACH: Success with no transport channel type switching
tc_8_2_4_17	Transport channel reconfiguration from CELL_FACH to CELL_FACH: Success (Cell re-selection)
tc_8_2_4_18	Transport Channel Reconfiguration from CELL_DCH to CELL_DCH: Success (Subsequently received)
tc_8_2_4_19	Transport Channel Reconfiguration from CELL_FACH to CELL_DCH: Success (Subsequently received)
tc_8_2_4_20	Transport Channel Reconfiguration from CELL_DCH to CELL_PCH: Success
tc_8_2_4_21	Transport Channel Reconfiguration from CELL_DCH to URA_PCH: Success
tc_8_2_4_22	Transport Channel Reconfiguration from CELL_FACH to CELL_PCH Success
tc_8_2_4_23	Transport Channel Reconfiguration from CELL_FACH to URA_PCH Success
tc_8_2_5_1	Transport format combination control in CELL_DCH: restriction
tc_8_2_5_2 tc_8_2_5_4	Transport format combination control in CELL_DCH: release a restriction Transport format combination control in CELL_DCH: Failure (Invalid message reception and Invalid
tc_8_2_6_1	configuration) Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to
tc_8_2_6_2	another frequency): Success Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to
tc_8_2_6_3	another frequency): Failure (Unsupported configuration) Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to
tc_8_2_6_4	another frequency): Failure (Physical channel failure and reversion to old channel) Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to another frequency): Failure (Physical channel failure and reversion failure)
tc_8_2_6_5	Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to
tc_8_2_6_6	another frequency): Failure (Incompatible simultaneous reconfiguration) Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to
tc 8 2 6 7	another frequency): Failure (Invalid message reception and Invalid configuration) Physical channel reconfiguration for transition from CELL_DCH to CELL_FACH: Success
tc_8_2_6_7 tc_8_2_6_8	Physical channel reconfiguration for transition from CELL_DCH to CELL_FACH: Success (Cell re-
to 9 2 6 0	Selection) Delivered channel reconfiguration for transition from CELL_EACH to CELL_DCH: Success
tc_8_2_6_9	Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Success

Test case	Description
tc_8_2_6_10	Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Failure (Unsupported
	configuration)
tc_8_2_6_11	Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Failure (Physical
tc_8_2_6_12	channel failure and reversion to old configuration) Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Failure (Physical
10_0_2_0_12	channel failure and reversion failure)
tc_8_2_6_13	Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Failure (Incompatible
	simultaneous reconfiguration)
tc_8_2_6_14	Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Failure (Invalid
tc_8_2_6_15	message reception and Invalid configuration) Physical channel reconfiguration for transition from CELL_FACH to CELL_FACH (Hard handover to
10_8_2_0_15	another frequency): Success
tc_8_2_6_16	Physical channel reconfiguration for transition from CELL_FACH to CELL_FACH: (Cell re-selection)
tc_8_2_6_17	Physical channel reconfiguration for transition from CELL_DCH to CELL_DCH (Hard handover to
	another frequency): Success (Subsequently received)
tc_8_2_6_18	Physical channel reconfiguration for transition from CELL_FACH to CELL_DCH: Success (Subsequently received)
tc_8_2_6_19	Physical Channel Reconfiguration from CELL_DCH to CELL_PCH: Success
tc_8_2_6_20	Physical Channel Reconfiguration from CELL_DCH to URA_PCH: Success
tc_8_3_1_1	Cell Update: cell reselection in CELL_FACH
tc_8_3_1_2	Cell Update: cell reselection in CELL_PCH
tc_8_3_1_3	Cell Update: periodical cell update in CELL_FACH
tc_8_3_1_4 tc_8_3_1_5	Cell Update: periodical cell update in CELL_PCH and multiple cell update causes Cell Update: UL data transmission in URA_PCH
tc_8_3_1_6	Cell Update: UL data transmission in CELL_PCH
tc_8_3_1_9	Cell Update: re-entering of service area after T305 expiry and being out of service area
tc_8_3_1_10	Cell Update: expiry of T307 after T305 expiry and being out of service area
tc_8_3_1_11	Cell Update: Success after T302 time-out
tc_8_3_1_12	Cell Update: Failure (After Maximum Re-transmissions)
tc_8_3_1_13	Cell Update: Reception of Invalid CELL UPDATE CONFIRM Message Cell Update: Incompatible simultaneous reconfiguration
tc_8_3_1_14 tc_8_3_1_15	Cell Update: Unrecoverable error in Acknowledged Mode RLC
tc_8_3_1_16	Cell Update: cell reselection in CELL_FACH
tc_8_3_1_17	Cell Update: Failure (UTRAN initiate an RRC connection release procedure on CCCH)
tc_8_3_1_18	Cell Update: Radio Link Failure (T314>0, T315=0)
tc_8_3_1_20	Cell Update: Reception of CELL UPDATE CONFIRM Message that causes invalid configuration
tc_8_3_2_1 tc_8_3_2_2	URA Update: Change of URA URA Update: Periodical URA update and Reception of Invalid message
tc_8_3_2_3	URA Update: re-entering of service area after T305 expiry
tc_8_3_2_4	URA Update: loss of service after expiry of timers T307 and T305
tc_8_3_2_5	URA Update: Success after Confirmation error of URA-ID list
tc_8_3_2_6	URA Update: Failure (V302 is greater than N302: Confirmation error of URA-ID list)
tc_8_3_2_7	URA Update: Success after T302 timeout
tc_8_3_2_8 tc_8_3_2_9	URA Update: Failure (V302 is greater than N302:T302 timeout) URA Update: Failure (UTRAN initiate an RRC connection release procedure on CCCH)
tc_8_3_2_10	URA Update: Reception of URA UPDATE CONFIRM message that causes invalid configuration and
	invalid URA UPDATE CONFIRM message
tc_8_3_3_1	UTRAN Mobility Information: Success
tc_8_3_3_2	UTRAN Mobility Information: Failure (Invalid message reception and cell re-selection)
tc_8_3_4_1 tc_8_3_4_2	Active set update in soft handover: Radio Link addition Active set update in soft handover: Radio Link removal
tc_8_3_4_2	Active set update in soft handover: Radio Link removal Active set update in soft handover: Combined radio link addition and removal (active set is not full)
tc_8_3_4_4	Active set update in soft handover: Invalid Configuration
tc_8_3_4_5	Active set update in soft handover: Combined radio link addition and removal (active set is full)
tc_8_3_4_7	Active set update in soft handover: Invalid Message Reception
tc_8_3_7_1	Inter system handover from UTRAN/To GSM/Speech/Success
tc_8_3_7_2	Inter system handover from UTRAN/To GSM/Data/Same data rate/Success
tc_8_3_7_3 tc_8_3_7_4	Inter system handover from UTRAN/To GSM/Data/Data rate down grading/Success Inter system handover from UTRAN/To GSM/Speech/Establishment/Success
tc_8_3_7_5	Inter system handover from UTRAN/To GSM/Speech/Establishment/Gdccess
tc_8_3_7_6	Inter system handover from UTRAN/To GSM/Speech/Failure (L2 Establishment)
tc_8_3_7_7	Inter system handover from UTRAN/To GSM/Speech/Failure (L1 Synchronization)
tc_8_3_7_8	Inter system handover from UTRAN/To GSM/Speech/Failure (Invalid Inter-RAT message)

Test case	Description
tc_8_3_7_9	Inter system handover from UTRAN/To GSM/Speech/Failure (Unsupported configuration)
tc_8_3_7_10	Inter system handover from UTRAN/To GSM/Speech/Failure (Reception by UE in CELL_FACH)
tc_8_3_7_11	Inter system handover from UTRAN/To GSM/Speech/Failure (Invalid message reception)
tc_8_3_7_12	Inter system handover from UTRAN/To GSM/Speech/Failure (Physical channel Failure and Reversion
10_0_0_1	Failure)
	Measurement
tc_8_4_1_1	Measurement Control and Report: Intra-frequency measurement for transition from idle mode to
	CELL_DCH state
tc_8_4_1_2	Measurement Control and Report: Inter-frequency measurement for transition from idle mode to
	CELL_DCH state
tc_8_4_1_3	Measurement Control and Report: Intra-frequency measurement for transition from idle mode to
	CELL_FACH state
tc_8_4_1_4	Measurement Control and Report: Inter-frequency measurement for transition from idle mode to
	CELL_FACH state
tc_8_4_1_5	Measurement Control and Report: Intra-frequency measurement for transition from CELL_DCH to
	CELL_FACH state
tc_8_4_1_6	Measurement Control and Report: Inter-frequency measurement for transition from CELL_DCH to
	CELL_FACH state
tc_8_4_1_7	Measurement Control and Report: Intra-frequency measurement for transition from CELL_FACH to
	CELL_DCH state
tc_8_4_1_8	Measurement Control and Report: Inter-frequency measurement for transition from CELL_FACH to
	CELL_DCH state
tc_8_4_1_9	Measurement Control and Report: Unsupported measurement in the UE
tc_8_4_1_10	Measurement Control and Report: Failure (Invalid Message Reception)
tc_8_4_1_11	Measurement Control and Report: Compressed Mode Configuration Failure during radio bearer reconfiguration procedure
tc_8_4_1_12	Measurement Control and Report: Compressed Mode Configuration Failure during transport channel
10_0_4_1_12	reconfiguration procedure
tc_8_4_1_13	Measurement Control and Report: Compressed Mode Configuration Failure during physical channel
10_0_4_1_10	reconfiguration procedure
tc_8_4_1_14	Measurement Control and Report: Cell forbidden to affect reporting range
tc_8_4_1_15	Measurement Control and Report: Configuration Incomplete
10_0_1_10	Idle Mode Operations
tc_6_1_1_1	PLMN selection of RPLMN, HPLMN, UPLMN and OPLMN; Manual mode
tc_6_1_1_2	PLMN selection of "Other PLMN / access technology combinations"; Manual mode
tc_6_1_1_3	PLMN selection; independence of RF level and preferred PLMN; Manual mode
tc_6_1_1_4	PLMN selection of RPLMN, HPLMN, UPLMN and OPLMN; Automatic mode
tc_6_1_1_5	PLMN selection of "Other PLMN / access technology combinations"; Automatic mode
tc_6_1_1_6	UE will transmit only if PLMN available
tc_6_1_2_1	Cell reselection
tc_6_1_2_2	Cell reselection using Qhyst, Qoffset and Treselection
tc_6_1_2_3	HCS Cell reselection
tc_6_1_2_4	HCS Cell reselection using reselection timing parameters for the H criterion
tc_6_1_2_5	HCS Cell reselection using reselection timing parameters for the R criterion
tc_6_1_2_6	Emergency calls
tc_6_1_2_7	Emergency calls; Intra-frequency cell "Not allowed"
tc_6_2_1_1	Selection of the correct PLMN and associated RAT
tc_6_2_1_2	Selection of RAT for HPLMN; Manual mode
tc_6_2_1_3	Selection of RAT for UPLMN; Manual mode
tc_6_2_1_4	Selection of RAT for OPLMN; Manual mode
tc_6_2_1_5	Selection of "Other PLMN / access technology combinations"; Manual mode
tc_6_2_1_6	Selection of RAT for HPLMN; Automatic mode
tc_6_2_1_7	Selection of RAT for UPLMN; Automatic mode
tc_6_2_1_8	Selection of RAT for OPLMN; Automatic mode
tc_6_2_1_9	Selection of "Other PLMN / access technology combinations"; Automatic mode
tc_6_2_2_1	Cell reselection if cell becomes barred or S<0; UTRAN to GSM
tc_6_2_2_2	Cell reselection if cell becomes barred or C1<0; GSM to UTRAN
tc_6_2_2_3	Cell reselection timings; GSM to UTRAN

A.5 RLC ATS

The approved RLC test cases are listed.

Table A.5: RLC TTCN test cases

Test case	Description
tc_7_2_2_2	UM Segmentation and reassembly / Selection of 7 or 15 bit Length Indicators
tc_7_2_2_3	UM Segmentation / 7-bit Length Indicators / Padding
tc_7_2_2_4	UM Segmentation / 7-bit Length Indicators / LI = 0
tc_7_2_2_5	UM Segmentation / 7-bit Length Indicators / Invalid LI value
tc_7_2_2_6	UM Segmentation / 7-bit Length Indicators / LI value > PDU size
tc_7_2_2_7	UM Segmentation / 7-bit Length Indicators / First data octet LI
tc_7_2_2_8	UM Segmentation / 15-bit Length Indicators / Padding
tc_7_2_2_9	UM Segmentation / 15-bit Length Indicators / LI = 0
tc_7_2_2_10	UM Segmentation / 15-bit Length Indicators / One octet short LI
tc_7_2_2_11	UM Segmentation / 15-bit Length Indicators / Invalid LI value
tc_7_2_2_12	UM Segmentation / 15-bit Length Indicators / LI value > PDU size
tc_7_2_2_13	UM Segmentation / 15-bit Length Indicators / First data octet LI
tc_7_2_3_2	AM Segmentation and reassembly / Selection of 7 or 15 bit Length Indicators
tc_7_2_3_3	AM Segmentation / 7-bit Length Indicators / Padding or Piggy-backed Status
tc_7_2_3_4	AM Segmentation / 7-bit Length Indicators / LI = 0
tc_7_2_3_5	AM Segmentation / 7-bit Length Indicators / Reserved LI value
tc_7_2_3_6	AM Segmentation / 7-bit Length Indicators / LI value > PDU size
tc_7_2_3_7	AM Segmentation / 15-bit Length Indicators / Padding or Piggy-backed Status
tc_7_2_3_8	AM Segmentation / 15-bit Length Indicators / LI = 0
tc_7_2_3_9	AM Segmentation / 15-bit Length Indicators / One octet short LI
tc_7_2_3_10	AM Segmentation / 15-bit Length Indicators / Reserved LI value
tc_7_2_3_11	AM Segmentation / 15-bit Length Indicators / LI value > PDU size
tc_7_2_3_12	AM Correct use of Sequence Numbering
tc_7_2_3_13	AM Control of Transmit Window
tc_7_2_3_14	AM Control of Receive Window
tc_7_2_3_15	AM Polling for status / Last PU in transmission queue
tc_7_2_3_16	Polling for status / Last PU in retransmission queue
tc_7_2_3_17	AM Polling for status / Poll every Poll_PU Pus
tc_7_2_3_18	Polling for status / Poll every Poll_SDU SDUs
tc_7_2_3_19	AM Polling for status / Timer triggered polling (Timer_Poll_Periodic)
tc_7_2_3_20	AM Polling for status / Polling on Poll_Window% of transmission window
tc_7_2_3_21	AM Polling for status / Operation of Timer_Poll timer / Timer expiry
tc_7_2_3_22	AM Polling for status / Operation of Timer_Poll timer / Stopping Timer_Poll timer
tc_7_2_3_23	AM Polling for status / Operation of Timer_Poll timer / Restart of the Timer_Poll timer
tc_7_2_3_24	AM Polling for status / Operation of timer Timer_Poll_Prohibit
tc_7_2_3_25	AM Receiver Status Triggers / Detection of missing Pus
tc_7_2_3_26	AM Receiver Status Triggers / Operation of timer Timer_Status_Periodic
tc_7_2_3_27	AM Receiver Status Triggers / Operation of timer Timer_Status_Prohibit
tc_7_2_3_28	AM Status reporting / Abnormal conditions / Reception of LIST SUFI with Length set to zero
tc_7_2_3_29	AM Timer based discard, with explicit signalling / Expiry of Timer_Discard
tc_7_2_3_30	AM Timer based discard, with explicit signalling / Obsolete MRW_ACK
tc_7_2_3_31	AM Timer based discard, with explicit signalling / Failure of MRW procedure
tc_7_2_3_32	AM SDU discard after MaxDAT number of retransmissions
tc_7_2_3_33	AM Operation of the RLC Reset procedure / UE Originated
tc_7_2_3_34	AM Operation of the RLC Reset procedure / UE Terminated

A.6 MAC ATS

The approved MAC test cases are listed.

Table A.6: MAC TTCN test cases

Test case	Description
tc_7_1_1_2	DTCH or DCCH mapped to RACH/FACH / Invalid TCTF
tc_7_1_1_3	DTCH or DCCH mapped to RACH/FACH / Invalid C/T Field
tc_7_1_1_4	DTCH or DCCH mapped to RACH/FACH / Invalid UE ID Type Field
tc_7_1_1_5	DTCH or DCCH mapped to RACH/FACH / Incorrect UE ID

A.7 BMC ATS

The approved BMC test cases are listed.

Table A.7: BMC TTCN test cases

Test case	Description
tc_7_4_2_1	UE in RRC Idle mode
tc_7_4_2_2	UE in RRC Connected mode, state CELL_PCH
tc_7_4_2_3	UE in RRC Connected mode, state URA_PCH
tc_7_4_3_1	Reception of certain CBS message types

A.8 PDCP ATS

The approved PDCP test cases are listed.

Table A.8: PDCP TTCN test cases

Test case	Description
tc_7_3_2_1_1_1	IP Header Compression and PID assignment /UE in RLC AM /Transmission of uncompressed Header (1. Test procedure: Transmission of uncompressed IP header packets using PDCP Data PDU)
tc_7_3_2_1_1_2	IP Header Compression and PID assignment /UE in RLC AM /Transmission of uncompressed Header (2. Test procedure: Transmission of uncompressed IP header packets using No Header PDU)
tc_7_3_2_1_2	IP Header Compression and PID assignment /UE in RLC AM/Transmission of compressed Header
tc_7_3_2_2_1_1	IP Header Compression and PID assignment /UE in RLC UM /Transmission of uncompressed Header (1. Test procedure: Transmission of uncompressed IP header packets using PDCP Data PDU)
tc_7_3_2_2_1_2	IP Header Compression and PID assignment /UE in RLC UM /Transmission of uncompressed Header (2. Test procedure: Transmission of uncompressed IP header packets using No Header PDU)
tc_7_3_2_2_2	IP Header Compression and PID assignment /UE in RLC UM/Transmission of compressed Header
tc_7_3_2_2_3	Extension of used compression methods
tc_7_3_2_2_4	Compression type used for different entities
tc_7_3_2_2_5	Reception of not defined PID values
tc_7_3_3_1	Data transmission if lossless SRNS Relocation is supported
tc_7_3_3_2	Synchronisation of PDCP sequence numbers

A.9 RAB ATS

The approved RAB test cases are listed.

Table A.9: RAB TTCN test cases

Test case	Description
tc_14_2_4	Conversational / speech / UL:12_2 DL:12_2 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_5	Conversational / speech / UL:10_2 DL:10_2 kbps / CS RAB + UL:3_4 DL: 3_4 kbps SRBs for

Test case	Description
111111111	DCCH
tc_14_2_6	Conversational / speech / UL:7_95 DL:7_95 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for
	DCCH
tc_14_2_7	Conversational / speech / UL:7_4 DL:7_4 kbps / CS RAB+ UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_8	Conversational / speech / UL:6_7 DL:6_7 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_9	Conversational / speech / UL:5_9 DL:5_9 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_10	Conversational / speech / UL:5_15 DL:5_15 kbps / CS RAB + UL:1_7 DL:1_7 kbps SRBs for DCCH
tc_14_2_11	Conversational / speech / UL:4_75 DL:4_75 kbps / CS RAB + UL:1_7 DL:1_7 kbps SRBs for DCCH
tc_14_2_12	Conversational / unknown / UL:28_8 DL:28_8 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_13_1	Conversational / unknown / UL:64 DL:64 kbps / CS RAB / 20 ms TTI
tc_14_2_13_2	Conversational / unknown / UL:64 DL:64 kbps / CS RAB / 40 ms TTI
tc_14_2_14_1	Conversational / unknown / UL:32 DL:32 kbps / CS RAB / 20 ms TTI
tc_14_2_14_2	Conversational / unknown / UL:32 DL:32 kbps / CS RAB / 40 ms TTI
tc_14_2_15	Streaming / unknown / UL:14_4/DL:14_4 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_16	Streaming / unknown / UL:28_8/DL:28_8 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_17	Streaming / unknown / UL:57_6/DL:57_6 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_18	Streaming / unknown / UL:0 DL:64 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_19	Streaming / unknown / UL:64 DL:0 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_20	Streaming / unknown / UL:0 DL:128 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_21	Streaming / unknown / UL:128 DL:0 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_22	Streaming / unknown / UL:0 DL:384 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_23_1	Interactive or background / UL:32 DL:8 kbps / PS RAB / (TC,10 ms TTI)
tc_14_2_23_2	Interactive or background / UL:32 DL:8 kbps / PS RAB / (TC, 20 ms TTI)
tc_14_2_23_3	Interactive or background / UL:32 DL:8 kbps / PS RAB / (CC, 10 ms TTI)
tc_14_2_23_4	Interactive or background / UL:32 DL:8 kbps / PS RAB / (CC, 20 ms TTI)
tc_14_2_24_1	Interactive or background / UL:64 DL:8 kbps / PS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH / TC
tc_14_2_24_2	Interactive or background / UL:64 DL:8 kbps / PS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH / CC
tc_14_2_25_1	Interactive or background / UL:32 DL: 64 kbps / PS RAB / (TC, 10 ms TTI)
tc_14_2_25_2	Interactive or background / UL:32 DL: 64 kbps / PS RAB / (TC, 20 ms TTI)
tc_14_2_25_3	Interactive or background / UL:32 DL:64 kbps / PS RAB / (CC, 10 ms TTI)
tc_14_2_25_4	Interactive or background / UL:32 DL:64 kbps / PS RAB / (CC, 20 ms TTI)
tc_14_2_26	Interactive or background / UL:64 DL: 64 kbps / PS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_27	Interactive or background / UL:64 DL:128 kbps / PS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_28	Interactive or background / UL:128 DL:128 kbps / PS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_29	Interactive or background / UL:64 DL:144 kbps / PS RAB + UL:3_4 DL: 3_4 kbps SRBs for DCCH
tc_14_2_30	Interactive or background / UL:144 DL:144 kbps / PS RAB + UL:3_4 DL: 3_4 kbps SRBs for DCCH
tc_14_2_31_1	Interactive or background / UL:64 DL:256 kbps / PS RAB + UL:3_4 DL: 3_4 kbps SRBs for DCCH/ 10 ms TTI
tc_14_2_31_2	Interactive or background / UL:64 DL:256 kbps / PS RAB / 20 ms TTI
tc_14_2_32_1	Interactive or background / UL:64 DL:384 kbps / PS RAB / 10 ms TTI
tc_14_2_32_2	Interactive or background / UL:64 DL:384 kbps / PS RAB / 20 ms TTI
tc_14_2_33_1	Interactive or background / UL:128 DL:384 kbps / PS RAB / 10 ms TTI
tc_14_2_33_2	Interactive or background / UL:128 DL:384 kbps / PS RAB / 20 ms TTI
tc_14_2_34_1	Interactive or background / UL:384 DL:384 kbps / PS RAB / 10 ms TTI
tc_14_2_34_2	Interactive or background / UL:384 DL:384 kbps / PS RAB / 20 ms TTI
tc_14_2_35_1	Interactive or background / UL:64 DL:2048 kbps / PS RAB / 10 ms TTI
tc_14_2_35_2	Interactive or background / UL:64 DL:2048 kbps / PS RAB / 20 ms TTI
tc_14_2_36_1	Interactive or background / UL:128 DL:2048 kbps / PS RAB / 10 ms TTI
tc_14_2_36_2	Interactive or background / UL:128 DL:2048 kbps / PS RAB / 20 ms TTI
tc_14_2_37_1	Interactive or background / UL:384 DL:2048 kbps / PS RAB / 10 ms TTI
tc_14_2_37_2	Interactive or background / UL:384 DL:2048 kbps / PS RAB / 20 ms TTI
tc_14_2_40	Conversational / speech / UL:12_2 DL:12_2 kbps / CS RAB + Interactive or background / UL:64
	DL:64 kbps / PS RAB+ UL:3_4 DL: 3_4 kbps SRBs for DCCH
tc_14_2_45	Conversational / speech / UL:12_2 DL:12_2 kbps / CS RAB + Streaming / unknown / UL:57_6 DL:57_6 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH
tc_14_2_49_1	Conversational / speech / UL:12_2 DL:12_2 kbps / CS RAB + Conversational / unknown / UL:64 DL:64 kbps / CS RAB / 20 ms TTI
L	

Test case	Description
tc_14_2_50_1	Conversational / unknown / UL:64 DL:64 kbps / CS RAB + Conversational / unknown / UL:64 DL:64 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH / 20 ms TTI
tc_14_2_50_2	Conversational / unknown / UL:64 DL:64 kbps / CS RAB + Conversational / unknown / UL:64 DL:64 kbps / CS RAB + UL:3_4 DL:3_4 kbps SRBs for DCCH / 40 ms TTI
tc_14_2_51_1	Conversational / unknown / UL:64 DL:64 kbps / CS RAB / 20 ms TTI + Interactive or background / UL:64 DL:64 kbps / PS RAB
tc_14_2_53_1	Conversational / unknown / UL:64 DL:64 kbps / CS RAB / 20 ms TTI + Interactive or background / UL:128 DL:128 kbps / PS RAB

Total of test cases: 609

Ready for verification (Green): 576